





# **Documenting Historic Structures**

Jessica Fortney Historic Preservation Specialist Northern Bedrock Historic Preservation Corps April 23, 2020 at 10am

- Photo Documentation
  - I am not a professional photographer

• Photos with Reports





# What do you want to say with your pictures and documentation?

- A snapshot in time
- To create a story
- Social media/Website







# Tools, Materials, Brain Power


- Camera
- Tripod (with level)
- Sun or Cloudy day if outside
- Step stool
- Scale



### Camera

- Simple camera
- Cell Phone





### **Tripod with Level**






## Tools, Materials, Brain Power

### Camera

- Tripod (with level)
- Sun or Cloudy day if outside
- Step stool
- Scale



### **Shadow? Cloudy or Sunny Day**





Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades

### Tools, Materials, Brain Power

### Camera

- Tripod (with level)
- Sun or Cloudy day if outside
- Step stool
- Scale



### **Step Stool and Scale**









Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades

### **Point and Label**














### Views

- 8 views
  - We can't move everything
- Context
- Character Defining Features
- Document issues









HISTORIC PRESERVATION CORPS











### Views

### 8 views

- We can't move everything
- Context
- Character Defining Features
- Document issues



### Feature, issue



A CARTHERN BEORD A CARTHERN B

Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades














A CREATE A C



A STATE OF CORPS



OTHERN BEORD CALL OF THE CALL

### **Character Defining Feature**






ORTHERN BEORGE HISTORIC PRESERVATION CORPS












### **Before and Afters**







# **Back to the Computer**

- Folders
  - What makes sense
- Spreadsheets
   Photo logs, tables
- Labels
  - North, South, Front, Back, rotten log
- Document
  - Date, square footage, work done





### **Folders**



ARTHERN BEORO

Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades

### **Spreadsheets**

• Photo Log

| _ | A         | В              |   | C            | D             |   | E          |   | F                             |    | G<br>Photo Description   |  |
|---|-----------|----------------|---|--------------|---------------|---|------------|---|-------------------------------|----|--|--|
| 1 | Date      | Photographer 🚽 |   | Photo ID     | Stage of Work |   | Building   |   | Work Project (Area of Work) 🌱 |    |  |  |
| 2 | 3/13/2017 | Kate Ruble     | ٠ | P3130042.JPG | Site Visit    | * | Pump House | Ŧ | Power Lines *                 |    | On top of hill above Pump House,<br>inspecting power line damage |  |
| 3 | 3/13/2017 | Kate Ruble     | ÷ | P3130043.JPG | Site Visit    | ÷ | Pump House | * | Power Lines                   |    | On top of hill above Pump House,<br>inspecting power line damage |  |
| 4 | 3/13/2017 | Kate Ruble     |   | P3130044.JPG | Site Visit    | * | Pump House | * | Power Lines                   | *  | Coil of old power lines taken down                               |  |
| 5 | 3/13/2017 | Kate Ruble     | * | P3130045.JPG | Site Visit    | • | Pump House | ÷ | Power Lines                   |    | Broken power line post on top of hill<br>behind pump house       |  |
| 6 | 3/13/2017 | Kate Ruble     |   | P3130046.JPG | Site Visit    |   | Pump House | Ŧ | Power Lines                   | ×. | Inspection of broken power lines                                 |  |
| 7 | 3/13/2017 | Kate Ruble     | ٣ | P3130047.JPG | Site Visit    |   | Pump House | * | Power Lines                   | ٣  | Inspection of broken power lines                                 |  |
| 8 | 3/13/2017 | Kate Ruble     | * | P3130048.JPG | Site Visit    | * | Pump House | - | Power Lines                   |    | Broken power line post on top of hill<br>behind pump house       |  |



### **Table – Conditions Assessments**

Biogrowth on the roof needs to be removed

| North Wall East Wall South Wa |                               | South Wall             | West Wall                               | Northeast  | Northwest  | Southeast  | Southwest  |  |
|-------------------------------|-------------------------------|------------------------|---|------------|------------|------------|------------|--|
| 4 cracks in foundation        |                               |                        | 6L - Hole<br>in log                     | 1R - Check | 7R - Check | 4L - Check | 3R- Rot    |  |
|                               | 1 crack in<br>foundation      | 3 cracks in foundation | Sliding<br>boat door<br>needs<br>repair | 3R - Check | 9R - Check |            | 7R- Check  |  |
|                               | Door needs<br>new<br>hardware |                        | 2 cracks in foundation                  | 7R - Check | 4L - Check |            | 2L - Check |  |
|                               |                               |                        |   | 5L - Check | 6L - Check |            | 4L - Check |  |
|                               |                               |                        |   | 6L - Check |            |            | 5L - Chec  |  |
|                               |                               |                        |   | 7L - Check |            |            | 6L - Check |  |
|                               |                               |                        |   |            |            |            | 8L- Check  |  |
|                               |                               |                        |   |            |            |            | 9L- Check  |  |
|                               |                               |                        |   |            |            |            | 10L- Check |  |

\*All numbers are counting the logs from the foundation up

**Building Interior:** 

PRESERVATION CORPS Cracks in concrete floor

Northern Bedrock Historic Preservation Corps


Building a pathway to the preservation trades



PRESERVATION CORPS



### **Floor Plan**





Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades

# **Back to the Computer**


### • Folders

- What makes sense

- Spreadsheets

   Photo logs, tables
- Labels
  - North, South, Front, Back, rotten log
- Document
  - Date, square footage, work done





### Label your photos

**District Office Exterior South 6.JPG** 

District Office Exterior South.JPG

◎☆☆☆☆☆ District Office Exterior West 2.JPG

District Office Exterior West 3.JPG



District Office Exterior West 4.JPG

**District Office Exterior West 5.JPG** 

District Office Exterior West 6.JPG

District Office Exterior West.JPG



Northern Bedrock Historic Preservation Corps

Building a pathway to the preservation trades

## A chance to Document other things

- Square Footage
  - Easy for bidding, contractors, paint supplies, number of acres
- Date
  - Everything should have a date
- Make sure to document work done



### **Friendly Reminder**





ORTHERN BRODE ORTHERN BRODE A HISTORIC PRESERVATION CORPS



### Jessica Fortney Historic Preservation Specialist/Program Manager Northern Bedrock Historic Preservation Corps www.northernbedrockcorps.org IG: northernbedrockcorps Facebook: Northern Bedrock Historic Preservation Corps

Halfway Ranger Station



